

Date Completed: _____ Failure Code: _____

Completed By : _____ Signature : _____

Accepted By : _____ Signature : _____

**** Delay Codes Legend ****

W=Whse C=CrSp T=Tag TL=Tool P=Plan

**** Record Time Daily ****

[illegible]

**** IMPORTANT NOTICE ****

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



IP7_032341

** Work Order Parts List **

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1 18821	BLADE, CIRCULAR SAW	S 278671	03/21/04	EA	3	0	3
2 23301	STEEL, CHANNEL	S 278632	03/21/04	FT	0	0	0
3 23302	STEEL, CHANNEL	S 278632	03/21/04	FT	100	0	100
4 50064	TAPE, TEFLON	S 278633	03/21/04	RL	6	0	6
5 76741	BLADE, METAL CUTTING	S 278673	03/21/04	EA	3	0	3
6 DIRECT	SERVICE: INSTALL WINDBOX BAFFLE SYSTEM AS PER DESIGN FROM AD	04-37722	03/22/04	EA	1	0	1

IP7_032342